MIKIOI STREET

265°40'

asphalt

<u>edge pavement</u>

70.71

 $\frac{1}{2}$ " pipe (fnd)

edge pavement

NOEAU STREET

 $\frac{1}{2}$ " pipe (fnd) $\frac{up/sl}{s}$



TMK: (3) 2-2-059: 006

TRUE NORTH SCALE: 1in.=20ft

concrete rubble masonry

concrete

driveway

street light utility pole

water meter


found guy wire

WAIAKEA RESIDENCE LOTS UNIT I (PLAT 3.2 H.H)

SITUATED AT WAIAKEA, SOUTH HILO, ISLAND OF HAWAII, HAWAII

Please note the following improvements along the property line

- (1) Loose rock wall along the West boundary is entirely within neighboring Lot 61.
- 2) Metal fence line along the West boundary is entirely within subject Lot 63.
- 3 CRM wall along the South boundary is entirely within adjacent Lots 4 and 5.
- 1. Azimuths shown on this map are referred to Government Survey Triangulation Station "HALAI" ...
- 2. Adjoining lot information has been taken from records filed at the real property mapping branch.



SURVEY MAP

LOT 8
HILO SCATTERED LOTS
KAUMANA SUBDIVISION
UNIT I (F.P. 2476)

SITUATED AT KAUMANA AND PONAHAWAI, SOUTH HILO, ISLAND OF HAWAII, HAWAII 1810 UHALOA ROAD



AUSTIN, TSUTSUMI, & ASSOCIATES INC. 501 SUMNER STREET, SUITE 521

HONOLULU, HI 96817

THIS WORK WAS PREPARED BY ME OR UNDER MY SUPERVISION.

LICENSED PROFESSIONAL LAND SURVEYOR CERTIFICATE No. 9826 EXP. 04/22

Please note the following improvements along the property line

- (1) CRM wall along the North boundary is entirely within subject Lot 8.
- 2 CRM wall along the Southerly boundary is entirely within subject Lot 8.
- 3 Concrete driveway along the West boundary is entirely within subject Lot 8

NOTES:

- 1. Azimuths shown on this map are referred to Government Survey Triangulation Station "KAUMANA".
- 2. Adjoining lot information has been taken from records filed at the real property mapping branch.
- 3. Found property boundaries differ from record as shown on the map.
- 4. ____ Denotes no vehicular access permitted.